



1) It is easiest to lace the Canopy with the frame on a table at a comfortable working height.

2) Fig#1 shows how to center the canopy on the frame using the 8 ties supplied. Remove each tie as you lace to that grommet.

3) Fig#2 shows how to run the lacing. Lace one grommet at the time pulling all the cord thru before moving to the next grommet.



Fig#1, Tie Placement.




Fig#2, Lacing and Knotting.

4) Fig#2 Just snug the cord until you complete lacing taking care to keep the canopy centered.

5) Fig#2 When completely laced, tighten the lacing so there is no slack in the canopy. The nylon cord will stretch and require re-tightening in a few hours.

6) Fig#2 Finish and knot the ends as shown. You will have 1 half hitch on top and 1 on the bottom of the same grommet. Work the knot close to the grommet, cut and melt a ball of hard nylon on the end of the cord with a flame to prevent un-raveling.

7) Fig#3 This is how your lacing should look when finished.



Fig#3, Finished.



C.E. SMITH, Co.